

# PRODEMAND

YMMS: 2005 Chrysler 300 C  
Engine: 5.7L Eng  
VIN:

Jul 20, 2020  
License:  
Odometer:

## Possible Causes

Possible Causes
EXHAUST LEAK
ENGINE MECHANICAL PROBLEM
1/2 O2 SENSOR
(K141) O2 SENSOR 1/2 SIGNAL CIRCUIT
(K299) O2 1/2 HEATER CONTROL CIRCUIT
(K904) O2 DOWNSTREAM RETURN CIRCUIT
FUEL CONTAMINATION

**Always perform the PRE-DIAGNOSTIC TROUBLESHOOTING PROCEDURE before proceeding.**