

DATE	ECU	DTC	DESCRIPTION
8/24/2021	PDM	B1F02-12	Mirror Vertical Motor Control-Circuit Short to Battery
8/24/2021	PDM	B1F02-13	Mirror Vertical Motor Control-Circuit Open
8/24/2021	ORC	B212D-13	Ignition Run Only Input-Circuit Open
8/24/2021	TCM	P1915	Transmission Inhibited Remote Start
8/24/2021	TCM	P1DC7	Clutch Temp Threshold Achieved- Shift Time Reduction
8/24/2021	TCM	U0140	Lost Communication with Body Control Module
8/24/2021	TCM	U0212	Lost Communication With Steering Column Control Module
8/24/2021	SCCM	U1175	Lost Ignition Status Message
8/24/2021	RFH	U1197	Security Seed Response Not Received from ECM/PCM
8/24/2021	TCM	U11E4	CAN Communication Messages Missing
8/24/2021	TCM	U0100	Lost Communication with ECM/PCM "A"
8/24/2021	TCM	U0103	Lost Communication With Electric Gear Shift Module
9/7/2021	TCM	P1DC7-00	Clutch Temp Threshold Achieved- Shift Time Reduction
9/7/2021	TCM	U0103-00	Lost Communication With Electric Gear Shift Module
9/7/2021	TCM	U0140-00	Lost Communication With Body Control Module
9/7/2021	PCM	U0140	Lost Communication With Body Control Module
9/7/2021	DTCM	U0121	Lost Communication With Anti-Lock Brake System (ABS) Control Mo
9/7/2021	DTCM	U0100	Lost Communication with ECM/PCM "A"
9/7/2021	BCM	U0151-00	Lost Communication With Occupant Restraint Controller (ORC)
9/7/2021	ACC	U0101-00	Lost Communication With TCM

Status

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored

Stored